SEAL OF APPROVAL

SoRite, LLC

The SoRite Corporation
4721 Trousdale Dr. Suite 116, Nashville, TN 37220, United States

Piss Off

Dilution Rate (oz./gal.): RTU

Cleaning Instructions:

1. Remove Solids: 2. Pet Urine: Blot up as much pee as you can. 3. Saturate stains with solution. Let stand for 10 minutes. 4. Wipe with white cloth. 5. Repeat and wipe with white cloth.

Cleaning Solution Program

Certification From: 07/29/2025

Type: Pet Stain and Odor Remover

Certification Expiration: 09/30/2026



100 S HAMILTON STREET DALTON, GA 30720-4612 **UNITED STATES**

SOA-certified products are required by the US Green Building Council's LEED v4.1 under the program's Green Cleaning Equipment provision.

Certification Number: SOA101163



WWW.CARPET-RUG.ORG